

Oil Field Environmental Incident Summary

Incident: 20150125151755 **Date/Time of Notice:** 01/25/2015 15:17

Responsible Party: Secure Energy Services

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: 13 MILE SWD 1

Field Name: TYRONE

Well File #: 90159

Date Incident: 1/25/2015

Time Incident: 02:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 101

Sec: 12

Qtr: NW SW

Location Description: Lane Surface near SW corner of tank farm secondary containment.

Submitted By: John Albert

Received By:

Contact Person: Josh Mossbrucker
555 17TH ST STE 800
DENVER, CO 80202-3908

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 150 Feet

Distance Nearest Water Well: 300 Feet

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	3	Barrels		

Brine

Other

Description of Other Released Contaminant:

Standing meltwater on Facility surface; approx 2-3bbl will also be removed and disposed of

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Minimal risk, pooling is limited to facility site and exists in a low spot in grade. Spill was contained in shovel berm and cleanup is underway.

Areal Extent:

Potential Environmental Impacts:

Minimal potential environmental impacts. Contaminated areas are within site confines and are contained to a small area. Full cleanup should be possible within 48 hours.

Action Taken or Planned:

Vac truck on site at time of spill was called in to remove spill and contaminated meltwater to FST waste tanks. Contaminated soils will be removed to low-side bin and grade will be restored with clean topsoil.

Wastes Disposal Location: Waste liquids will be offloaded and processed on site. Solids waste will be removed to low side storage on site, evaluated and removed at earliest opportunity.

Agencies Involved:**Updates**

Date: 1/26/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.